

NO BARRIERS

CONNECTING PEOPLE
ON ALL LEVELS

THE CHALLENGES

Poor Accessibility

The ADA entrance is the furthest point from the sanctuary. The rear ramp is too steep and is not compliant. The only weekday entrance is not ADA accessible.

Outdated Restrooms

The only ADA-compliant restrooms are on the Fellowship Hall level, reachable only by stairs or chair lift. Other restrooms are small, outdated, and hard to find.

Limited Use

There is no dedicated kitchen storage, running water, or refrigeration in our Welcome Center. Volunteers disrupt Sunday School classes to prepare beverages and resupply the coffee bar.

Disjointed Floor Plan

Our nursery is not conveniently located near the Sanctuary. Administrative offices are not positioned for efficiency. Several spaces are underutilized.

HIGH-IMPACT IMPROVEMENTS

- **Elevator Installation:** A centrally located four-level elevator providing full access to our children's ministry, ground level entrance, sanctuary, gym, and balcony.
- **Accessible Facilities:** Construction of modern, ADA compliant restrooms near the Sanctuary and Welcome Center.
- **Welcome Center Expansion:** A redesigned Welcome Center with a dedicated hospitality kitchen and improved flow.
- **Ministry Reconfiguration:** Relocating the Nursery closer to the Sanctuary and reorganizing administrative offices to improve collaboration, communication, and mission alignment.

*East Main Mission:
"To honor God by being and making
more disciples of Jesus Christ."*

NEXT STEPS

- 1 Congregational Engagement
- 2 Finalize Architectural Proposal
- 3 Congregational Vote on August 30th

ESTIMATED COST

\$1,000,000



EAST MAIN
CHURCH